

Action	Assigned to	Date added	Date completed	Notes
Replace garage doors at 5B, 1M, 2M, 3M, 1268W and 1316 W.	Rick	7/25/2018		Contract assigned to Precision Door
Replace side garage doors at 10 C, 28 C, 7M and 17 M.	Rick	5/17/2018		Needed at 10 C, 28 C, 7M and 17 M . Awarded to Rochester Colonial for \$3992. Likely Nov install date for: 10 CC, 7M, 17M , 1260 W. Ron suggests 28 C needs it more then 1260 W, or else do both.
Get quote from Genesee Tree (Ed LaPore) for tree trimming	Rick	6/25/2018		Walkaround with Ed LaPore took place on 10/5/2018. Ed said would take 4-5 days to lift up all trees in fronts. Est cost about \$1000/day
Revise Homeowner's Guide	Bob	6/25/2018		Draft has been circulated
Revise Deck Policy	Ron	7/27/2018		-Approved with changes. Ron to edit and distribute
Schedule and plan for special meeting re: road dedication	Board	9/10/2018		Meeting scheduled for Nov 6 , Malone Room, Victor Library. Draft of approval form sent to Falvey and Kocher, 10/3/2018 Draft is on website.
FYI: Cracks were filled and roads sealcoated in 2014 by Magic Seal for \$7,621.	Board	10/7/2018		Should we plan on doing this again next year?
Attend CAI-WNY vendors' show	Board	10/25/2018		10/25, 4:30pm, Burgandy Basin Inn Do individuals need to send in form?
Open Work Order: #722: Uneven sidewalk pavers at 6 Cambridge Circle	Rick	7/26/2018	Done	10/12/2018 - Looks ok to me. Can mark this as completed
Open Work Order: #783, Loose siding at 2 Medford Way		6/14/2018	done	It now looks ok as of 10/12/2018
Open Work Order: #789: Shingle tabs folded back at 24 Cambridge Circle		6/14/2018	Done	It now looks ok as of 10/12/2019
Open Work Order; #798: Circular vent rotted at 12 Cambridge Circle		6/14/2018		10/12/2018: Need confirmed
Open Work Order: #800: Rotted side door molding at 28 Cambridge Circle		6/14/2018		Confirmed. See "Replace side garage doors..." above
Open Work Order: #801: Basement window on south side has rotted frame at 1 Medford		6/14/2018		Confirmed on 10/12. Entire window my have to be replaced.
Open Work Order: #803 Unsealed Dryer vent at 3 Medford Way on South side.		6/14/2018		-Need confirmed on 12/12
Open Work Order: 804 Rotted side door molding at 7 Medford Way		6/14/2018		7 Medford Way

